K+S
SERVICES
a SunSource Company

Telesis Marking Systems Repair Capabilities

K+S has the ability to repair and fully test Telesis PINSTAMP® controllers and marking head components. Telesis dot peen marking systems are used in a wide array of manufacturing environments. Controllers are compatible with multiple marking heads and do not require a PC. Marking heads may be stationary or portable depending on the application.

Controllers

Marking Heads

TMP1700

TMP3200

TMP4500E