

Fanuc I Pendant LCD Replacement

The original LCD for the I pendant part no. A05B-2255-C101 has been discontinued by the OEM. As a result, there is no repair offered by the OEM for this model only an exchange. K+S has had the LCD's reverse engineered and manufactured exclusively. K+S can offer a repair for these pendants rather than forcing an exchange.

