




- SOUTHGATE, MI ● TAYLOR, MI ● KOKOMO, IN ● LAWTON, OK ● ROCKY HILL, CT ● OAKVILLE, ON ● MONTREAL, QC ●
- SALAMANCA, MX ● APODACA, MX ● TAMWORTH, UK ● NAPAJEDLA, CZ ● SINT – TRUIDEN, BE ● OŚWIĘCIM, PL

Fanuc I Pendant LCD Replacement

The original LCD for the I pendant part no. A05B-2255-C101 has been discontinued by the OEM. As a result, there is no repair offered by the OEM for this model only an exchange. K+S has had the LCD's reverse engineered and manufactured exclusively. K+S can offer a repair for these pendants rather than forcing an exchange.



ALL UNITS ARE SYSTEM TESTED

***12 MONTH IN-SERVICE WARRANTY**
Unless otherwise stated at time of quotation

***NO CHARGE EVALUATION**
Priority repair orders may incur in evaluation fee