


### Hitachi Welder and Torch Head Assembly

B.L. Super-Torch Head Assembly...Model P50B04007DCL60

K+S is capable of Testing and Repairing the Hitachi DT-CAT3U 200 Inverter Pulse MIGWelder, and the B.L. Super Torch Head Assembly.

Complete dynamic testing is performed on both of these units, as well as all the preventive maintenance required before testing. AC frequency, arc characteristics, wire diameter, and gas check are all confirmed by a series of potentiometers on the welders front panel. The servo motor itself is fully load tested, confirmed for proper feedback, and run to top speed in our state of the art motor repair lab.



YN7000H6PS  
Servo Motor

YN7008HB4  
3 Torch Neck